

LEBRAVO®

Name of article:	Aurora
Leather type:	Performance smooth bovine leather
Average hide size:	22-25 / 50-55 SqFt Half hides/Full hides
Thickness:	1,2/1,4mm
Tan Type:	Chorme Tanning
Characteristics:	Wipeable, washable, stain resistant
Origin:	Europe, Tanned in Italy
Embossing:	No embossing

Ideal for contract and hospitality project as well as residential

Staining Agent	Gray Scale	Staining Agent	Gray Scale
<i>Oil</i>	4/5	<i>Butter</i>	4/5
<i>Orange Juice</i>	4/5	<i>Coca Cola</i>	4/5
<i>Chocolate</i>	4/5	<i>Condensed Milk</i>	4/5
<i>Coffee</i>	4	<i>Ketchup</i>	4
<i>Red Wine</i>	3/4	<i>Water</i>	5

Parameter Description	Unit of measure	Value	Method
<i>Dry flexing endurance</i>	<i>Cicli</i>	50000 (no break)	UNI EN ISO 5402-1: 2017
<i>Colour fastness to artificial light until the contrast on the specimen is equal to gray scale 3</i>	<i>Blu Scale</i>	6/7	UNI EN ISO B02: 2014
<i>Single edge strenght</i>	<i>N</i>	17	UNI EN ISO 3377-1: 2012
<i>Dry colour fastness to-and-fro rubbing to faded (grain)</i>	<i>Cicli</i>	1000	UNI EN ISO 11640: 2018
<i>Change in colour (dry)</i>	<i>Gray scale</i>	4/5	UNI EN ISO 11640: 2018
<i>Staining colour of the felt (dry)</i>	<i>Gray scale</i>	4/5	UNI EN ISO 11640: 2018
<i>Wet colour fastness to-and-fro rubbing to faded (grain)</i>	<i>Cicli</i>	100	UNI EN ISO 11640: 2018
<i>Change in colour (wet)</i>	<i>Gray scale</i>	4	UNI EN ISO 11640: 2018
<i>Staining colour of the felt (wet)</i>	<i>Gray scale</i>	3/4	UNI EN ISO 11640: 2018
<i>Alcaline sweat colour fastness to-and-fro rubbing to faded (grain)</i>	<i>Cicli</i>	50	UNI EN ISO 11640: 2018
<i>Change in colour (alcaline sweat)</i>	<i>Gray scale</i>	4	UNI EN ISO 11640: 2018
<i>Staining colour of the felt (alcaline swet)</i>	<i>Gray scale</i>	3	UNI EN ISO 11640: 2018
<i>Burning behaviour to cigarette and match flame test</i>		<i>Pass</i>	BS 5852:1979 CA TB 117

Cleaning and maintenance :

1. In the event of a stain, remove dirt with a cloth.
2. For more intense stains, pour a little water with neutral soap (do not use invasive products: use specific products for leather care) or ethyl alcohol for stained marks.
3. Dry with cloth, dabbing with delicate circular movements
4. Once dry, your leather will be as good as new!